

# 1999 Annual Report

ACT / 007 / 019

Centennial Mining

File in:

☐ Confidential

☐ Shelf

☒ Expandable

Refer to Record No. 0008 Date 05/01/2000

In C 0070019 2000 Incomeing

For additional information

### GENERAL INFORMATION

1. Permit Number	ACT 007/019		
2. Mine Name	Centennial		
3. Permittee Name	ANDALEX Resources, Inc.		
4. Operator Name (if other than Permittee)	Same		
5. Permit Expiration Date	January, 2002		
6. Company Representative, Title	Michael W. Glasson, Senior Geologist		
7. Phone Number	(435) 637-5385		
8. Fax Number	(435) 637-8860		
9. Mailing Address	P.O. Box 902		
	Price, Utah		
	84501		
10. Resident Agent, Title	Michael W. Glasson, Resident Agent		
Mailing Address	Same		

RECEIVED

MAY 04 2000

DIVISION OF  
OIL, GAS AND MINING

### IDENTIFICATION OF OTHER PERMITS

Identify other permits which are required in conjunction with mining and reclamation activities.

Permit Type	ID Number	Description	Expires on
1. MSHA Mine ID(s)	42-02028	Aberdeen Mine	N/A
	42-01474	Pinnacle Mine	N/A
2. MSHA Impoundment(s)	No		
3. NPDES/UPDES Permit(s) (water)	UTG04000 8	Sediment Pond Discharge (2 each), Mine Discharge (2 each)	April 30, 2003
4. PSD (Air ) Permit(s)	DEQ	Air Quality Approval Order	N/A

1999 ANNUAL REPORT	Centennial	ACT 007/019	Page 2
5.			
6.			

## CERTIFIED REPORTS

List the certified inspection reports as required by the rules and under the approved plan which must be periodically submitted to the Division. Specify whether the information is included as APPENDIX A to this Annual Report or currently ON FILE with the Division.

Certified Reports:	Reports Required?		INCLUDED or ON FILE w/DOGM?			Comments
	YES	NO	YES	NO	ON FILE	
1. Excess Spoil Piles		XX		XX		
2. Refuse Piles		XX		XX		
3. Impoundments		XX		XX		
4.						
5.						

## REPORTING OF OTHER TECHNICAL DATA

List other technical data and information as required under the approved plan which must be periodically submitted to the Division. Specify whether the information is included as APPENDIX B to this Annual Report or currently ON FILE with the Division.

Technical Data:	Reports Required?		INCLUDED or ON FILE w/DOGM?			Comments
	YES	NO	YES	NO	ON FILE	
1. Climatological Data		XX		XX		
2. Subsidence Monitoring Data	XX		XX			
3. Vegetation Monitoring Data		XX		XX		
4. Raptor Data		XX		XX		
5. Soils Monitoring Data		XX		XX		
6. Water Monitoring Data	XX		XX			
First Quarter Report	XX		XX			
Second Quarter Report	XX		XX			
Third Quarter Report	XX		XX			
Fourth Quarter Report	XX		XX			
7. Geological/Geophysical Data		XX		XX		
8. Engineering Data		XX		XX		
9. Other Data						



# APPENDIX A

## Certified Reports

Excess Spoil Piles  
Refuse Piles  
Impoundments

as required under R645-301-514

## CONTENTS

None

# **APPENDIX B**


## **Reporting of Technical Data**

including monitoring data, reports, maps, and other information  
as required under the approved plan  
or as required by the Division

in accordance with the requirements of R645-301-130 and R645-301-140.

## **CONTENTS**

Quarterly Water Monitoring  
Sedimentation Pond Inspection  
Subsidence Monitoring



**ANDALEX**  
RESOURCES, INC.

P.O. BOX 902  
PRICE, UTAH 84501  
PHONE (435) 637-5385  
FAX (435) 637-8860

**M E M O R A N D U M**


**TO:** DOGM, General Inspection File  
**FROM:** Michael W. Glasson *MWG*  
**DATE:** April 30, 1999  
**SUBJECT:** 1999 1st Quarter Water Monitoring, Minesite

---

Water Monitoring- 1st Quarter, 1999

7-1	No Flow	03/31/99
8-1	No Flow	03/31/99
17-1	No Flow	03/31/99
17-2	No Flow	03/31/99
S18-1	No Flow	03/31/99
18-2	No Flow	03/31/99
18-3	No Flow	03/31/99
18-4	No Flow	03/31/99
S25-1	Negligible Flow	03/31/99
25-2	No Flow	03/31/99
Well #1	Sampled	03/01/99

cc: Jim Smith, DOGM  
File



**ANDALEX**  
RESOURCES, INC.

PO. BOX 902  
PRICE, UTAH 84501  
PHONE (435) 637-5385  
FAX (435) 637-8860

**MEMORANDUM**

**TO:** DOGM, General Inspection File  
**FROM:** Michael W. Glasson *mi*  
**DATE:** September 1, 1999  
**SUBJECT:** 1999 2nd Quarter Water Monitoring, Minesite


---

*sub*  
Water Monitoring- ~~1st~~ Quarter, 1999

7-1	No Flow	06/30/99
8-1	No Flow	06/30/99
17-1	No Flow	06/30/99
17-2	No Flow	06/30/99
S18-1	Sampled	04/22/99
18-2	No Flow	06/30/99
18-3	No Flow	06/30/99
18-4	No Flow	06/30/99
S25-1	Negligible Flow	06/30/99
25-2	No Flow	06/30/99
Well #1	Sampled	06/30/99

cc: Jim Smith, DOGM  
File





**ANDALEX**  
RESOURCES, INC.

P.O. BOX 902  
PRICE, UTAH 84501  
PHONE (435) 637-5385  
FAX (435) 637-8860

**MEMORANDUM**


**TO:** DOGM, General Inspection File  
**FROM:** Michael W. Glasson  
**DATE:** October 22, 1999  
**SUBJECT:** 1999 3rd Quarter Water Monitoring, Minesite

---

Water Monitoring- 3rd Quarter, 1999

7-1	No Flow	09/30/99
8-1	No Flow	09/30/99
17-1	No Flow	09/30/99
17-2	No Flow	09/30/99
S18-1	Sampled	07/13/99
18-2	No Flow	09/30/99
18-3	No Flow	09/30/99
18-4	No Flow	09/30/99
S25-1	Negligible Flow	09/30/99
25-2	No Flow	09/30/99
Well #1	Sampled	09/30/99

cc: Jim Smith, DOGM  
File



**ANDALEX**  
RESOURCES, INC.

P.O. BOX 902  
PRICE, UTAH 84501  
PHONE (435) 637-5385  
FAX (435) 637-8860

**MEMORANDUM**

**TO:** DOGM, General Inspection File

**FROM:** Michael W. Glasson

**DATE:** January 31, 2000

**SUBJECT:** 1999 4th Quarter Water Monitoring, Minesite

---

Water Monitoring- 4th Quarter, 1999

7-1	No Flow	12/30/99
8-1	No Flow	12/30/99
17-1	No Flow	12/30/99
17-2	No Flow	12/30/99
S18-1	No Flow	12/30/99
18-2	No Flow	12/30/99
18-3	No Flow	12/30/99
18-4	No Flow	12/30/99
S25-1	Negligible Flow	12/30/99
25-2	No Flow	12/30/99
Well #1	Sampled	12/30/99

cc: Jim Smith, DOGM  
File

# SEDIMENTATION POND

## Inspection Report

### Pond B

Date: 3/30/99

Inlet & Outlet Conditions:

All OK

Erosion Problems:

None Observed

Embankment Stability:

All Stable

Water Level:

High

Weather Conditions:

Windy

Additional Comments:

Time of Inspection:

11:30

Person Conducting Inspection:

Michael W. Kline

# SEDIMENTATION POND

## Inspection Report

### Pond C

Date: 3/30/99

Inlet & Outlet Conditions:

All OK

Erosion Problems:

None Observed

Embankment Stability:

All Stable

Water Level:

High

Weather Conditions:

Warm, Windy

Additional Comments:

Time of Inspection:

11:30

Person Conducting Inspection:

Michael W. Clam

# SEDIMENTATION POND

## Inspection Report

### Pond E

Date: 3/30/99

Inlet & Outlet Conditions:

Erosion Problems:

Embankment Stability:

Water Level:

Weather Conditions:

Additional Comments:

Time of Inspection:

Person Conducting Inspection:

1st Quarter

All OK

None Observed

Stable

dry

Warm, Windy

Clean out - 1999

11:30

Michael W. Elam

**ANDALEX RESOURCES, INC.**  
**1999 ANNUAL POND INSPECTION REPORT**

POND: Sed. Basin "B"LOCATION: Centennial

<b>IMPOUNDMENTS</b>	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	0.538 acre feet.
(6) Monitoring Procedures	Sediment Level. Cleanout at 50% accumulation. (Between 1 and 2)

<b>SEDIMENT PONDS ONLY</b>	
(7) Sediment Accumulation (Elevation)	7077.70 - #2
(8) Sediment Cleanout Level (Elevation)	7081.0 - #2
(9) Principle Spillway (Elevation)	7077.0 - #2
(10) Emergency Spillway (Elevation)	7078.0 - #1
(11) Existing Sediment Capacity (To Cleanout)	0.262 acre feet.

<b>GENERAL</b>	
(12) Comments/Recommendations	Cell B4 - Cleaned 1997 Cell B3 - Cleaned 1997 Cell B2 - Cleaned 1997 Cell B1 - 0% Sed.

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 (Signature)

10/12/99

(Date)



**ANDALEX RESOURCES, INC.**  
**1999 ANNUAL POND INSPECTION REPORT**

POND: Sed. Pond "C"LOCATION: Centennial

<b>IMPOUNDMENTS</b>	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	1.72 acre feet.
(6) Monitoring Procedures	U.P.D.E.S Quarterly Inspection.

<b>SEDIMENT PONDS ONLY</b>	
(7) Sediment Accumulation (Elevation)	7045.8
(8) Sediment Cleanout Level (Elevation)	7046.2
(9) Principle Spillway (Elevation)	7051.9
(10) Emergency Spillway (Elevation)	7053.7
(11) Existing Sediment Capacity (To Cleanout)	0.031 acre feet.

<b>GENERAL</b>	
(12) Comments/Recommendations	Interior Partially Vegetated. No Discharge. Inlets O.K.

**STATEMENT**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

  
(Signature)

10/12/99  
(Date)



**ANDALEX RESOURCES, INC.**  
**1999 ANNUAL POND INSPECTION REPORT**

POND: Sed. Pond "E"LOCATION: Centennial

<b>IMPOUNDMENTS</b>	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Damp.
(5) Existing Storage Capacity	1.929 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

<b>SEDIMENT PONDS ONLY</b>	
(7) Sediment Accumulation (Elevation)	6946.3
(8) Sediment Cleanout Level (Elevation)	6946.5
(9) Principle Spillway (Elevation)	6957.6
(10) Emergency Spillway (Elevation)	6958.6
(11) Existing Sediment Capacity (To Cleanout)	0.027 acre feet.

<b>GENERAL</b>	
(12) Comments/Recommendations	Sediment near cleanout level. No Discharge. Inlets O.K. Outlets O.K.

**STATEMENT**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

  
(Signature)

10/12/99

(Date)





**SEDIMENTATION POND**  
**Inspection Report**  
**Pond B**

<b>Date:</b>	6/30/99
<b>Inlet &amp; Outlet Conditions:</b>	All OK
<b>Erosion Problems:</b>	None observed
<b>Embankment Stability:</b>	Embankments are stable
<b>Water Level:</b>	0
<b>Weather Conditions:</b>	clear, hot
<b>Additional Comments:</b>	
<b>Time of Inspection:</b>	11:30
<b>Person Conducting Inspection:</b>	Mick W. Elam

# SEDIMENTATION POND

## Inspection Report

### Pond C

<b>Date:</b>	6/30/99
<b>Inlet &amp; Outlet Conditions:</b>	All OK
<b>Erosion Problems:</b>	None Observed
<b>Embankment Stability:</b>	Embankments are stable
<b>Water Level:</b>	0
<b>Weather Conditions:</b>	clear hot
<b>Additional Comments:</b>	
<b>Time of Inspection:</b>	11:30
<b>Person Conducting Inspection:</b>	Mike W. ...

**SEDIMENTATION POND**  
**Inspection Report**  
**Pond E**

<b>Date:</b>	6/30/99
<b>Inlet &amp; Outlet Conditions:</b>	All OK
<b>Erosion Problems:</b>	None Observed
<b>Embankment Stability:</b>	All embankments appear stable
<b>Water Level:</b>	approx. 1' in bottom
<b>Weather Conditions:</b>	clear, hot
<b>Additional Comments:</b>	Needs cleaning
<b>Time of Inspection:</b>	11:30
<b>Person Conducting Inspection:</b>	Michael McGowan

# SEDIMENTATION POND

## Inspection Report

### Pond B

Date:	9/30/99
Inlet & Outlet Conditions:	All OK
Erosion Problems:	Small erosion below cell 4 at outlet
Embankment Stability:	Same
Water Level:	0
Weather Conditions:	Clear, warm
Additional Comments:	
Time of Inspection:	1100
Person Conducting Inspection:	Michael Williams

**SEDIMENTATION POND**  
**Inspection Report**  
**Pond C**

Date:	9/30/99
Inlet & Outlet Conditions:	All OK
Erosion Problems:	None Observed
Embankment Stability:	Stable
Water Level:	0
Weather Conditions:	Clear, warm
Additional Comments:	
Time of Inspection:	1100
Person Conducting Inspection:	Michael W. Gamm

**SEDIMENTATION POND**  
**Inspection Report**  
**Pond E**

Date:	9/30/99
Inlet & Outlet Conditions:	Small repair on NE inlet
Erosion Problems:	None observed
Embankment Stability:	Stable
Water Level:	e
Weather Conditions:	Clear, warm
Additional Comments:	
Time of Inspection:	1100
Person Conducting Inspection:	Michael W. Glanville

# SEDIMENTATION POND

## Inspection Report

### Pond B

4th 1/4

Date:	12/30/99
Inlet & Outlet Conditions:	All OK
Erosion Problems:	None observed
Embankment Stability:	All embankments OK
Water Level:	None in any cell
Weather Conditions:	clear, warm
Additional Comments:	
Time of Inspection:	1300
Person Conducting Inspection:	Michael W. Blanton

# SEDIMENTATION POND

## Inspection Report

### Pond C

4th 1/4

Date:	12/30/99
Inlet & Outlet Conditions:	Fixed small erosion on road inlet
Erosion Problems:	None except noted above
Embankment Stability:	OK
Water Level:	Ø
Weather Conditions:	Clear, Warm
Additional Comments:	
Time of Inspection:	1300
Person Conducting Inspection:	Michael W. Blanton



# SEDIMENTATION POND

## Inspection Report

### Pond E

4th 1/4

Date:	12/30/99
Inlet & Outlet Conditions:	Dug out road inlet - silted
Erosion Problems:	None observed
Embankment Stability:	OK
Water Level:	Approx 6"
Weather Conditions:	Clear, warm
Additional Comments:	Will clean out this spring or summer; near cleanout point
Time of Inspection:	1300
Person Conducting Inspection:	Michael W. Glendon

*Andalex Resources, Inc.  
Centennial Project  
Sedimentation Pond Inspection Report*

POND: Sediment Pond "E"

DATE: 12/17/99

<i>Inlet &amp; Outlet Conditions:</i>	<i>O.K. - Culverts/Ditches/Spillway open.</i>
<i>Erosion Problems:</i>	<i>None Noted.</i>
<i>Embankment Stability:</i>	<i>Stable - Mostly Incised.</i>
<i>Water Level:</i>	<i>Approximately 3" Snow/Ice.</i>
<i>Weather Conditions:</i>	<i>Cloudy/Cold.</i>
<i>Additional Comments:</i>	<i>0.18' to Sediment Cleanout. Sediment Cleanout is 60% of maximum sediment level. Should be O.K. until spring.</i>

Time of Inspection: 11:25 a.m.

Person Conducting Inspection: Dan W. Guy 

Note: Annual Pond Inspection was on 10/12/99. Sediment level was re-checked per Mike Glasson's request, to see if capacity would be O.K. until spring. Pond capacity is adequate based on measurements.

**ANDALEX RESOURCES, INC.**  
**1999 ANNUAL POND INSPECTION REPORT**

**POND:** Sed. Basin "B"

**LOCATION:** Centennial

**IMPOUNDMENTS**

(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	0.538 acre feet.
(6) Monitoring Procedures	Sediment Level. Cleanout at 50% accumulation. (Between 1 and 2)

**SEDIMENT PONDS ONLY**

(7) Sediment Accumulation (Elevation)	7077.70 - #2
(8) Sediment Cleanout Level (Elevation)	7081.0 - #2
(9) Principle Spillway (Elevation)	7077.0 - #2
(10) Emergency Spillway (Elevation)	7078.0 - #1
(11) Existing Sediment Capacity (To Cleanout)	0.262 acre feet.

**GENERAL**

(12) Comments/Recommendations	Cell B4 - Cleaned 1997 Cell B3 - Cleaned 1997 Cell B2 - Cleaned 1997 Cell B1 - 0% Sed.
-------------------------------	---

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
(Signature)

10/12/99

(Date)



**ANDALEX RESOURCES, INC.**  
**1999 ANNUAL POND INSPECTION REPORT**

**POND:** Sed. Pond "C"

**LOCATION:** Centennial

**IMPOUNDMENTS**

(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	1.72 acre feet.
(6) Monitoring Procedures	U.P.D.E.S Quarterly Inspection.

**SEDIMENT PONDS ONLY**

(7) Sediment Accumulation (Elevation)	7045.8
(8) Sediment Cleanout Level (Elevation)	7046.2
(9) Principle Spillway (Elevation)	7051.9
(10) Emergency Spillway (Elevation)	7053.7
(11) Existing Sediment Capacity (To Cleanout)	0.031 acre feet.

**GENERAL**

(12) Comments/Recommendations	Interior Partially Vegetated. No Discharge. Inlets O.K.
-------------------------------	--

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
(Signature)

10/12/99  
(Date)



**ANDALEX RESOURCES, INC.**  
**1999 ANNUAL POND INSPECTION REPORT**

**POND:** Sed. Pond "E"

**LOCATION:** Centennial

<b>IMPOUNDMENTS</b>	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Damp.
(5) Existing Storage Capacity	1.929 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

<b>SEDIMENT PONDS ONLY</b>	
(7) Sediment Accumulation (Elevation)	6946.3
(8) Sediment Cleanout Level (Elevation)	6946.5
(9) Principle Spillway (Elevation)	6957.6
(10) Emergency Spillway (Elevation)	6958.6
(11) Existing Sediment Capacity (To Cleanout)	0:027 acre feet.

<b>GENERAL</b>	
(12) Comments/Recommendations	Sediment near cleanout level. No Discharge. Inlets O.K. Outlets O.K.

**STATEMENT**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

  
(Signature)

10/12/99  
(Date)



# Bruce T. S. Ware

REGISTERED LAND SURVEYOR

RT. 1, BOX 146 H-2

HELPER, UTAH 84526

Phone 637-2620 Oct. 3, 1999

Andalex Resources Inc.

Attn: Mike Glasson

P. O. Box 902

Price, UT 84501

Dear Mr. Glasson,

As you requested I surveyed your Companie's Subsidence Monitoring Points in September 1999. I have calculated the survey and find that there has been no movement horizontally or vertically since they were established. A visual inspection was made when walking between Subsidence points and no subsidence was seen. Four new points were established for the longwall subsidence for next year.

Sincerely

*Bruce T S Ware*

# Bruce T. S. Ware

REGISTERED LAND SURVEYOR

RT. 1, BOX 146 H-2

HELPER, UTAH 84526

Phone 637-2620

Oct. 3, 1999

Andalex Resources Inc.

Attn: Mike Glasson

P. O. Box 902

Price, UT 84501

Dear Mr. Glasson,

The following is a list of the Subsidence points I surveyed;

Station	Northing	Easting	Elevation
Rebar on Ridge	505,141.92	2,217,261.07	8,241.62 Control
Yellow Rebar	507,073.57	2,223,128.18	8,534.90 Control
S-10	507,824.28	2,217,196.61	8,594.59 Control
1A	504,057.30	2,216,581.05	8,147.11
1	502,940.35	2,216,278.99	8,178.26
4	503,237.80	2,221,322.47	8,285.25
11	498,937.95	2,218,688.70	7,671.20
9	506,252.70	2,221,663.42	8,544.09
5	504,194.50	2,224,747.31	8,001.91
7	502,013.02	2,225,964.69	8,102.92
13	500,747.10	2,228,007.65	7,854.71
S20	510,331.03	2,217,642.94	8,573.96
S24	513,030.96	2,217,476.03	8,425.50
S31	506,353.14	2,217,377.10	8,386.60
S30	506,015.22	2,215,357.97	8,117.72
S21	514,581.51	2,214,957.03	8,489.59
S23	514,248.42	2,215,475.07	8,363.47
S25	515,214.09	2,209,764.93	8,424.72
S26	514,518.44	2,212,435.50	8,365.79
S27	512,807.91	2,213,702.09	8,366.59
S28	511,498.36	2,209,969.87	8,669.25
S16(Graves)	508,650.51	2,210,725.76	8,809.50
S17(L3)	508,190.52	2,213,802.49	8,624.51
99-1	508,942.06	2,215,064.02	8,572.53
99-2	509,023.26	2,218,625.10	8,551.25
99-3	502,705.15	2,213,465.80	7,616.70
99-4	501,719.15	2,213,898.70	7,212.65

Sincerely

*Bruce T. S. Ware*

# **APPENDIX C**

**Legal, Financial, Compliance and Related Information**

**Annual Report of Officers**

as submitted to the Utah Department of Commerce

and other changes in ownership and control information  
as required under R645-301-110.

## **CONTENTS**

**Utah Dep't. Of Commerce Officers**



In person: 160 East 300 South, 1st Floor  
Salt Lake City, Utah 84111

Fax: (801) 530-6111

Web site: <http://www.commerce.state.ut.us>

# PROFIT CORPORATION ANNUAL REPORT

**FILED**

MAR 23 2000



**THIS FORM MUST BE COMPLETED IN FULL** All profit corporations must file their annual reports and corrections within the month of their anniversary date. Failure to do so will result in Delinquency, Revocation or Involuntary Dissolution of the corporate charter.

CORPORATION FILE # 080962

INCORPORATED OR  
QUALIFIED DATE 3 / 79  
MONTH YEAR

1. CORPORATE NAME ANDALEX Resources, Inc.  
2. REGISTERED AGENT John S. Kirkham  
3. REGISTERED OFFICE ADDRESS 201 S. Main Street, Suite 1100  
4. CITY, STATE & ZIP Salt Lake City, UT 84111 **UTAH**

WHEN CHANGING THE REGISTERED AGENT THE NEW AGENT MUST SIGN

5. INCORPORATED IN THE STATE AND UNDER THE LAWS OF: Delaware  
3. ADDRESS OF THE PRINCIPAL OFFICE IN THE HOME STATE 45 W. 10000 S., Suite 401  
Sandy, UT 84070

## 7. BUSINESS PURPOSE:

**DOMESTIC, PROFIT CORPORATIONS ARE REQUIRED TO LIST A CORPORATE OFFICER.**

### OFFICERS

3. PRESIDENT Douglas H. Smith  
ADDRESS 45 W 10000 S. Ste 401  
CITY Sandy STATE UT ZIP 84070  
9. VICE PRESIDENT Samuel C. Quigley  
ADDRESS 45 W 10000 S., Ste. 401  
CITY Sandy STATE UT ZIP 84070  
10. SECRETARY John Bradshaw  
ADDRESS 45 W 10000 S., Ste. 401  
CITY Sandy STATE UT ZIP 84070  
11. TREASURER \_\_\_\_\_  
ADDRESS \_\_\_\_\_  
CITY \_\_\_\_\_ STATE \_\_\_\_\_ ZIP \_\_\_\_\_

**ALL DOMESTIC CORPORATIONS MUST LIST THREE (3) DIRECTORS, UNLESS THEY FALL UNDER THE EXCEPTIONS STATED IN SECTION 16-10a-803(1)(b)(i) or (ii).**

### DIRECTORS

12. DIRECTOR Douglas H. Smith  
ADDRESS 45 W 10000 S., Ste 401  
CITY Sandy STATE UT ZIP 84070  
13. DIRECTOR Peter B. Green  
ADDRESS 45 W 10000 S., Ste 401  
CITY Sandy STATE UT ZIP 84070  
14. DIRECTOR Ronald C. Beedie  
ADDRESS 45 W 10000 S., Ste 401  
CITY Sandy STATE UT ZIP 84070

Under penalties of perjury and as an authorized officer, I declare that this annual report and, if applicable, the statement change of registered office and/or agent, has been examined by me and is, to the best of my knowledge and belief, true, correct, and complete.

15. BY \_\_\_\_\_

16. Title or Position \_\_\_\_\_

17. Date \_\_\_\_\_



IF THERE ARE NO CHANGES FROM THE PREVIOUS YEAR, AND YOU HAVE ALL CORPORATE REQUIREMENTS FILLED PERTAINING TO OFFICER, AND DIRECTOR INFORMATION YOU MAY COMPLETE THE COUPON BELOW, DETACH IT FROM THIS FORM, AND RETURN IT TO OUR OFFICE WITH YOUR PAYMENT.



# **APPENDIX D**

Mine Maps

as required under R645-301-525.270.

## **CONTENTS**

**Aberdeen 1999 Production**

# **APPENDIX E**

## **Other Information**

in accordance with the requirements of R645-301 and R645-302.

## **CONTENTS**